MENU V103 - DEFAULT SETTINGS SHADED

Address		
Address	DMX Address: 001-XXX Decimal Universe: XXXXX Net: XX Sub-Net: XX Universe: X Signal: DMX/WDMX/Art-Net/sACN	
Mode		
User Mode	Extend Mode User Mode A User Mode B User Mode C	
Edit User ModeA	Max channel PAN :	
Options		
Status	No DMX Mode Sun Protection Pan Reverse Tilt Reverse Pan Degree Tilt Degree Feedback Encoder Select Init PAN Init TILT Prerig INIT Reset Mode Pan/Tilt Spd CMY Spd Zoom/Focus Spd Reset LED Fade Hibernation DMX Output Data Collect 4G/Wifi Wifi Info	Close/Hold/Auto ON/OFF ON/OFF ON/OFF 630/540/360SC 270/540/360SC ON/OFF Photoelectric/Magnet ON/OFF ON/OFF ON/OFF Fast/All Rot Gobos Fast/Medium/Slow/FS Mode/Tracking 360 Fast/Medium/Slow Fast/Medium/Slow ON/OFF OFF, 01M~99M ON/OFF Agree/Disagree 4G/Wifi No/Yes
Service PIN	Service PIN Set IP Set Mask IP Reset From Mac DHCP Iot Lock Enable Cross Load SW Clr Error Info	Password = XXX xxx.xxx.xxx.xxx xxx.xxx.xxx.xxx ON/OFF ON/OFF ON/OFF ON/OFF ON/OFF
Fans Control	Fans Speed	Auto Stage Silence Super Silence
	Constant Fans	ON/OFF
Disp.Setting	Shutoff Time Flip Display Key Lock DispFlash	02~60m 05m ON/OFF ON/OFF ON/OFF
Temp. C/F	Celsius Fahrenheit	
Initial Pos.	PAN =XXX	
Wireless DMX	Activate WDMX Rest WDMX	
Dim Curve	Square Law Linear	
Refresh Select	1.2K 2.4K 16K 25K	
Defog	OFF Auto ON	
Reset P/T Fade	ON/OFF	
Illumination Limit	35m Distance/20m Distance/10m Distance	
Beam Mode	Limited Range/Full Range	
Trigger	DMX Value Disp. Set to Slave Auto Program	PAN..... Follow 1, Follow 2, Follow 3 Main/Alone
Reset Default	ON/OFF	

Options		
Reset User Set	Address	DMX address: 001-XXX Decimal Universe: XXXXX Net: XX Sub-Net: X Universe: X Signal: DMX/WDMX/Art-Net/sACN
	Mode	Extend Mode User Mode A User Mode B User Mode C
	Fans Speed	Auto Stage Silence Super Silence
	Constant Fans	ON/OFF
Info		
Time Info.	Current Time Ttl Life Hrs Last Run Hrs Laser Hours Timer PIN Clr Last Run	
Temp. Info	Head Temp.	
Humidity	x%	
Encoder Info	xxx	
Fan Info.	xxxx RPM	
Software Ver	V1.0.....	
Signal Quality	xxx	
Network	IP, Mask, Mac	
Error Info.	Error Record 1 :	
Blackout Info	Left.....	
SN	Product: xxxxx... Laser: xxxxx...	
RDM UID	UID: xxxx-xxxxxxxx	
Test		
Home	All Pan&Tilt Colour Gobo Other	
Test Channel	PAN	
Manual Ctrl.	PAN =XXX :	
Calibration	-Password- PAN :	
Cmy Comp	Service PIN C M :	
Magn Auto Cal	-Password- Calibration	
Magn P/T 50%	-Password- PAN TILT Calibration	
Gobo Replace	Gobo Wheel 1	
Preset		
Select Prog.	Prog. Part 1 = Program 1 ~ 10 Program 1 Prog. Part 2 = Program 1 ~ 10 Program 2 Prog. Part 3 = Program 1 ~ 10 Program 3	
Edit Prog.	Program 1 : Program 10	Program Test Step 01=SCxxx Step 64=SCxxx
Edit Scenes	Edit Scene 001 ~ Edit Scene 250	Pan,Tilt,..... --Fade Time-- --Scene Time-- Input By Outside
Scenes Input	XX~XX	