ARGO 6-WASH SOFTWARE VERSION HISTORY

VERSION	RELEASE DATE	DMX CHART	MODIFICATIONS
V100	2-Apr-23	V1	First release
V101	10-Jul-23	V1	Improved cooling
			Added NFC function
			synchronized changes on Argo 6 FX
			Added Sun protection
V102	20-Jul-23	V1	Added C33 and C06 options for "set LED BIN"
V103	19-Jul-24	V103	Change the mode name "Extended" to Extended Ring"
			Add Mode "Extended Pixel"
			Change dimmer curve to improve color shift problem in one situation
			Fix changing speed of chase cause a flash issue
			Fix a bug that clear UID SN MAC
			Fix a crossfade issue in channel 51
			Fix head temperature error issue
			Fix some white color in some effects
			Fix head temperature error
			Change Menu navigation
			Fix strobe and other issue
			Fix background issue when changing RGBW of chase effect
V104	6-Aug-24	V103	Fix the "DMX output" option
V130	25-Jun-25	V130	Fix a flash issue when using strobe, dim out and go to open with the dimmer at 0%
			Add Tungsten Simulation
			Improve Dimmer in Low level
			Correct the RDM Modele ID "AB13"
			Add Function to read and set address, universe and signal via Fixture Manager Software
V131	16-Mar-26	V130	Fixed a version mismatch that could occur under certain conditions.
			Improved RDM functionality.
			Added the “C04” LED bin option.
			Added the ability to read and set pixel address, universe, and signal via Fixture Manager.
			Added support for writing UID via NFC.
			Added protection to prevent damage when pan or tilt movement is obstructed (e.g., scenery in the way).

NOTE: Updating software does not restore factory default settings