DIABLO SOFTWARE VERSION HISTORY

VERSION	RELEASE DATE	DMX CHART	MODIFICATIONS
V100A	27-Sep-18		First Release
V102	27-Sep-19	V102	RDM function improved
			Framing range improved
			LED module protection in case of fan issue
			CMY curve improved
			Gobo wheel movement improved
			Base fan control improved
			Theatre Fan mode added
V104	25-Feb-20	V102	Battery bug fixed
			Battery activation time set to 6 seconds
			Fan modes improved
			Frost fade trouble fixed
			Color wheel indexing trouble fixed
V106	13-Nov-20	V106	Zoom & focus calibration range extended
			Super Silence Fan Mode added
			25 kHz PWM rate added
V201	23-Nov-20	V201	LED chase effects removed
			25 kHz PWM rate improved
V202	15-Jan-21	V201	Pre-rig Init menu added (Pan init then Tilt init)
			"Version Mismatch" message displayed in case of different firmware on PCBs LED module will be disabled
			Tilt angle selection added for pre-rig truss use
V203	15-Apr-21	V203	New Fan Modes improved Stage - Auto - Silence - Super Silence mode Constant Fans On or Off optionnal for Silence - Super Silence modes
V210	3-Nov-21	V203	New SW for new IC
			Not possible to downgrade to previous SW versions
V220	16-Nov-21	V203	New SW for new IC
			Not possible to downgrade to previous SW versions
V221	17-Jan-22	V203	Long press for Quick Menus (User settings)
			Update improvement
V222	15-Apr-22	V203	New SW for new IC
			Not possible to downgrade to previous SW versions
			Error Record function added
V223	12-Jul-22	V203	Minor Bug fix
V230	26-May-23	V203	New LCD Compatibility
V231	7-Nov-25	V231	Added more options for the Pre-Rig Init function.
			Added protection for situations where Pan or Tilt movement is blocked (for example, by locks or nearby scenery).
			Added new Pan/Tilt options in the Control Channel, and updated the speed setting names in the menu.
			Added a new Pan/Tilt Speed: FS Mode.
			Added a Reset Option in the main menu.
			Added “Unlink W-DMX” to the shortcut menu.
			Introduced a new display menu layout for easier navigation.

NOTE: Updating software does not restore factory default settings