AYRTON
Digital Lighting

ZONDA 3-WASH SOFTWARE VERSION HISTORY

VERSION	RELEASE DATE	DMX CHART	MODIFICATIONS
V110	22-Oct-22	V1	First version
V111	15-May-23	V1	Improve P/T reset issue
V112	19-Jul-24	V112	Correct DMX footprint on the Main Menu
			Change dimmer curve to improve color shift problem in one situation
			Fixed the bug on base fans abnormal speed in some setting.
			Removed the pop-up web info when NFC scaning
			Rename "Extended" as "Extended Ring"
			Add "Extended Pixel" Mode
			Add Reset IP Adresse From MAC menu
V113	6-Aug-24	V112	Fix the "DMX output" option
V115	20-Sep-24	V112	Improve PAN/TILT movment
V130	25-Jun-25	V130	Fix a flash issue when using strobe, dim out and go to open with the dimmer at 0%
			Add Tungsten Simulation
			Improve Dimmer in Low level
			Correct the RDM Modele ID "AB17"
			Add Function to read and set address, universe and signal via Fixture Manager Software

NOTE: Updating software does not restore factory default settings